

8.0 LIST OF PROPERTIES SURVEYED

| No. | Property Name | Street No. | Street Name | Municipality | Tax ID No. | Significance | Comments | Map Reference | Annotated List Page | Census Tract | Tax Credit Eligibility |
|-----|--------------------------------------|------------|-----------------|-------------------------|-----------------|--------------------------------------|---|---------------|---------------------|--------------|------------------------|
| 1 | IBM Research Laboratory | 22 | Adams Ave (A) | Village of Endicott | 157.07-1-4 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-1 | 5-14 | 134 | Y |
| 2 | IBM School Building #33 | 22 | Adams Ave (B) | Village of Endicott | 157.07-1-4 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-1 | 5-14 | 134 | Y |
| 3 | IBM Employee Cafeteria Building | 22 | Adams Ave (C) | Village of Endicott | 157.07-1-4 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-1 | 5-14 | 134 | Y |
| 4 | | 274 | Airport Rd | Town of Dickinson | 127.20-1-1 | Surveyed, appears not NR/SR Eligible | No industrial building/structure visible on site | DCKSN-1 | | | |
| 5 | | 3 | Alice St | City of Binghamton | 160.28-1-7 | Surveyed, appears not NR/SR Eligible | Lack of integrity | BING-1 | | | |
| 6 | Greenblott Metal Co. Inc. | 7 | Alice St | City of Binghamton | 160.28-1-6 | Surveyed, appears NR/SR Eligible | | BING-2 | 5-5 | 6 | Y |
| 7 | Binghamton Knitting Co. | 11 | Alice St | City of Binghamton | 160.28-1-5 | Surveyed, appears NR/SR Eligible | | BING-3 | 5-5 | 6 | Y |
| 8 | Faatz/Eagle Felt Mill | 80 | Arch St | Village of Johnson City | 143.65-3-1 | NR/SR Listed | Johnson City Historic District | JC-1 | 5-18 | 139 | Y |
| 9 | New Toe Box Company Factory | 19 | Avenue B | Village of Johnson City | 143.57-2-36 | NR/SR Listed | Johnson City Historic District | JC-2 | 5-18 | 139 | Y |
| 10 | | 720 | Azon Rd | Village of Johnson City | 143.45-1-15 | Surveyed, appears not NR/SR Eligible | Lack of integrity; modern materials | JC-3 | | | |
| 11 | | 723 | Azon Rd | Village of Johnson City | 143.45-1-12 | Surveyed, appears not NR/SR Eligible | Lack of integrity; modern materials | JC-4 | | | |
| 12 | | 6 | Badger Ave | Village of Endicott | 157.09-8-2 | Surveyed, appears not NR/SR Eligible | Significantly altered | END-2 | | | |
| 13 | Rubber Shoe Factory | 135 | Baldwin St | Village of Johnson City | 143.73-1-1 | NR/SR Listed | Shares tax parcel with 139 Baldwin; Johnson City HD | JC-5 | 5-18 | 138 | Y |
| 14 | Rubber Shoe Factory | 139 | Baldwin St | Village of Johnson City | 143.73-1-1 | NR/SR Listed | Shares tax parcel with 135 Baldwin; Johnson City HD | JC-6 | 5-19 | 140 | Y |
| 15 | Lestershire Spool Co. | 140 | Baldwin St | Village of Johnson City | 143.72-2-36 | NR/SR Listed | Johnson City Historic District | JC-7 | 5-19 | 140 | Y |
| 16 | | 27 | Barlow Rd | Town of Kirkwood | 162.05-1-8.1 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not meet NR criteria | KIRK-1 | | | |
| 17 | | 63 | Barlow Rd | Town of Kirkwood | 162.05-1-22 | Surveyed, appears not NR/SR Eligible | Significantly altered | KIRK-2 | | | |
| 18 | | 114 | Bevier St | City of Binghamton | 145.45-1-15 | Surveyed, appears not NR/SR Eligible | Does not meet NR criteria | BING-4 | | | |
| 19 | | 20 | Borden St | Village of Deposit | 203.06-1-12.1 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not meet NR criteria | DEPO-1 | | | |
| 20 | | 12 | Brandywine Ave | City of Binghamton | 160.28-1-31 | Surveyed, appears not NR/SR Eligible | Significantly altered | BING-5 | | | |
| 21 | | 107 | Brink St | Town of Union | 141.20-6-6 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | UNION-2 | | | |
| 22 | | 20 | Broad St | City of Binghamton | 145.37-1-12 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | BING-6 | | | |
| 23 | | 33 | Brookside Ave N | Town of Union | 142.17-6-44 | Surveyed, appears not NR/SR Eligible | Altered | UNION-3 | | | |
| 24 | Ansco Paper Plant (former) | 15 | Charles St | City of Binghamton | 144.78-1-20 | Surveyed, appears NR/SR Eligible | | BING-7 | 5-5 | 2 | Y |
| 25 | Ansco Power House (former) | 17 | Charles St | City of Binghamton | 144.78-1-20 | Surveyed, appears NR/SR Eligible | | BING-8 | 5-6 | 2 | Y |
| 26 | | 14 | Charlotte St | City of Binghamton | 160.21-2-8 | Surveyed, appears not NR/SR Eligible | Significantly altered | BING-9 | | | |
| 27 | | 1080 | Chenango St | Town of Fenton | 129.05-4-6 | Surveyed, appears not NR/SR Eligible | Altered; lack of integrity | FENT-1 | | | |
| 28 | IBM Factory Building #38 | 1101 | Clark St | Village of Endicott | 141.18-8-41 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-3 | 5-15 | 134 | Y |
| 29 | IBM Factory Building #46 | 1301 | Clark St | Village of Endicott | 141.18-8-49.111 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-4 | 5-15 | 134 | Y |
| 30 | IBM Factory Building #47 | 1901 | Clark St | Village of Endicott | 141.19-4-16 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-5 | 5-15 | 134 | Y |
| 31 | Ansco warehouse (former) | 219 | Clinton St | City of Binghamton | 144.77-1-11.2 | Surveyed, appears NR/SR Eligible | | BING-65 | 5-6 | 2 | Y |
| 32 | Crowley Milk Company | 135 | Conklin Ave | City of Binghamton | 160.58-1-4 | Surveyed, appears NR/SR Eligible | | BING-10 | 5-6 | 9 | Y |
| 33 | | 490 | Conklin Ave | City of Binghamton | 161.39-2-4 | Surveyed, appears not NR/SR Eligible | Appeared to be modern construction | BING-11 | | | |
| 34 | | 494 | Conklin Ave | City of Binghamton | 161.40-1-1 | Surveyed, appears not NR/SR Eligible | Appeared to be modern construction | BING-12 | | | |
| 35 | | 570 | Conklin Rd | Town of Conklin | 161.11-1-1 | Surveyed, appears not NR/SR Eligible | Lack of integrity; does not appear to meet NR criteria | CONK-1 | | | |
| 36 | | 42 | Corliss Ave | Village of Johnson City | 143.65-3-22 | Surveyed, appears not NR/SR Eligible | Determined not contributing to Johnson City Historic District | JC-8 | | | |
| 37 | | 44 | Corliss Ave | Village of Johnson City | 143.65-3-21 | Surveyed, appears not NR/SR Eligible | Determined not contributing to Johnson City Historic District | JC-9 | | | |
| 38 | Endicott-Johnson Pioneer Annex | 48 | Corliss Ave | Village of Johnson City | 143.65-3-19 | NR/SR Listed | | JC-10 | 5-19 | 139 | Y |
| 39 | Endicott-Johnson Jigger Factory | 96 | Corliss Ave | Village of Johnson City | 143.65-3-3 | NR/SR Listed | Johnson City Historic District | JC-11 | 5-20 | 139 | Y |
| 40 | | 174 | Court St | City of Binghamton | 160.42-1-15 | Surveyed, appears not NR/SR Eligible | Altered; lack of integrity | BING-13 | | | |
| 41 | Sheltered Workshops for the Disabled | 200 | Court St | City of Binghamton | 160.42-2-25 | Surveyed, appears NR/SR Eligible | | BING-14 | 5-7 | 11 | Y |
| 42 | | 30 | Crandall St | City of Binghamton | 160.22-1-32 | Surveyed, appears not NR/SR Eligible | Lack of integrity | BING-15 | | | |
| 43 | | 101 | Delaware Ave | Town of Union | 157.07-2-34 | Surveyed, appears not NR/SR Eligible | Unremarkable building; altered | UNION-4 | | | |
| 44 | | 100 | Duane Ave N | Village of Endicott | 156.12-3-44 | Surveyed, appears not NR/SR Eligible | Significantly altered; modern materials | END-6 | | | |
| 45 | | 1-3 | Duane Ave N | Village of Endicott | 156.12-4-12 | Surveyed, appears not NR/SR Eligible | Alterations; lack of integrity | END-7 | | | |
| 46 | W.A. Case & Sons Company | 2 | Eldredge St | City of Binghamton | 160.25-1-11 | Surveyed, appears NR/SR Eligible | | BING-16 | 5-7 | 5 | Y |
| 47 | | 54 | Eldredge St | City of Binghamton | 160.26-3-1 | Surveyed, appears not NR/SR Eligible | Modern materials; does not appear to meet NR criteria | BING-17 | | | |
| 48 | | 81 | Eldredge St | City of Binghamton | 160.26-2-19 | Surveyed, appears not NR/SR Eligible | Modern materials; does not appear to meet NR criteria | BING-18 | | | |
| 49 | | 93 | Ely St | City of Binghamton | 144.68-2-3 | Surveyed, appears not NR/SR Eligible | Unremarkable building; altered | BING-19 | | | |
| 50 | Wilson Electroplating Co. | 16 | Emma St | City of Binghamton | 143.75-1-16 | Surveyed, appears NR/SR Eligible | | BING-20 | 5-7 | 1 | Y |
| 51 | | 51 | Fairview Dr | Town of Kirkwood | 163.02-1-61 | Surveyed, appears not NR/SR Eligible | Lack of integrity | KIRK-3 | | | |
| 52 | | 627 | Field St | Village of Johnson City | 143.37-1-18 | Surveyed, appears not NR/SR Eligible | Unremarkable building; altered | JC-12 | | | |
| 53 | | 631 | Field St | Village of Johnson City | 143.37-1-19 | Surveyed, appears not NR/SR Eligible | Unremarkable building; altered | JC-13 | | | |

| No. | Property Name | Street No. | Street Name | Municipality | Tax ID No. | Significance | Comments | Map Reference | Annotated List Page | Census Tract | Tax Credit Eligibility |
|-----|---------------------------------|------------|----------------------|-------------------------|---------------|--------------------------------------|---|---------------|---------------------|--------------|------------------------|
| 54 | | 1 | Floral Ave | City of Binghamton | 143.67-3-8 | Surveyed, appears not NR/SR Eligible | Significantly altered | BING-21 | | | |
| 55 | | 2 | Floral Ave | City of Binghamton | 143.67-3-7 | Surveyed, appears not NR/SR Eligible | Lack of integrity; significantly altered | BING-22 | | | |
| 56 | | 57 | Franklin Ave | Town of Fenton | 129.05-4-48 | Surveyed, appears not NR/SR Eligible | Lack of integrity | FENT-2 | | | |
| 57 | | 404 | Franklin St E | Village of Endicott | 157.09-3-25 | Surveyed, appears not NR/SR Eligible | Alterations; lack of integrity | END-8 | | | |
| 58 | Machine Shop, NY Dept Public | 19 | Frederick St | City of Binghamton | 144.68-1-5 | Surveyed, appears not NR/SR Eligible | | BING-24 | 5-8 | 4 | Y |
| 59 | Engineering Dept, NY Dept | 67 | Frederick St | City of Binghamton | 144.67-3-53 | Surveyed, appears NR/SR Eligible | USN, No Determination | BING-23 | 5-8 | 4 | Y |
| 60 | | 80 | Frederick St | City of Binghamton | 144.76-1-4 | Surveyed, appears NR/SR Eligible | Lack of integrity; significant alterations | BING-25 | | | |
| 61 | | 117 | Frederick St | City of Binghamton | 144.68-2-13 | Surveyed, appears not NR/SR Eligible | Modern materials; does not appear to meet NR criteria | BING-26 | | | |
| 62 | | 135-137 | Frederick St | City of Binghamton | 145.61-1-20 | Surveyed, appears not NR/SR Eligible | Lack of integrity; alterations | BING-27 | | | |
| 63 | | 136 | Front St | Village of Deposit | 187.19-3-15 | Surveyed, appears not NR/SR Eligible | Lack of integrity; alterations | DEPO-2 | | | |
| 64 | | 140 | Front St | Village of Deposit | 187.19-3-16 | Surveyed, appears not NR/SR Eligible | Lack of integrity; alterations | DEPO-3 | | | |
| 65 | | 140 | Glendale Dr | Town of Union | 156.15-1-2 | Surveyed, appears not NR/SR Eligible | Lack of integrity; alterations | UNION-5 | | | |
| 66 | | 160 | Glendale Dr | Town of Union | 156.11-1-14 | Surveyed, appears not NR/SR Eligible | Altered | UNION-6 | | | |
| 67 | | 201 | Glendale Dr | Town of Union | 156.14-1-1.1 | Surveyed, appears not NR/SR Eligible | Modern materials; does not appear to meet NR criteria | UNION-7 | | | |
| 68 | | 301 | Glendale Dr | Town of Union | 156.11-1-1 | Surveyed, appears not NR/SR Eligible | Altered | UNION-8 | | | |
| 69 | Fairplay Caramels candy factory | 147 | Grand Ave | Village of Johnson City | 143.73-1-12.1 | Surveyed, appears NR/SR Eligible | USN, No Determination | JC-14 | 5-20 | 140 | Y |
| 70 | The Titchener Iron Works, Inc. | 21 | Griswold St | City of Binghamton | 144.84-3-13 | Surveyed, appears NR/SR Eligible | | BING-28 | 5-8 | 6 | Y |
| 71 | | 49 | Griswold St | City of Binghamton | 144.76-2-32 | Surveyed, appears not NR/SR Eligible | Altered | BING-29 | | | |
| 72 | | 15-19 | Griswold St | City of Binghamton | 160.28-1-26 | Surveyed, appears not NR/SR Eligible | Altered | BING-30 | | | |
| 73 | | 12 | Hall St | City of Binghamton | 160.59-1-9 | Surveyed, appears not NR/SR Eligible | Unremarkable building; lack of integrity | BING-31 | | | |
| 74 | T.C.M.F Metal Fabricators | 349 | Industrial Park Dr | Town of Kirkwood | 162.01-1-9 | Surveyed, appears NR/SR Eligible | | KIRK-4 | 5-22 | 126 | Y |
| 75 | | 29 | Industrial Park Dr S | Town of Kirkwood | 162.01-1-8 | Surveyed, appears not NR/SR Eligible | Unremarkable building; modern construction | KIRK-5 | | | |
| 76 | Budget Fence | 10 | Jackson St | City of Binghamton | 160.51-1-10 | Surveyed, appears NR/SR Eligible | | BING-32 | 5-9 | 9 | Y |
| 77 | | 1/2 | Jackson St | City of Binghamton | 160.51-1-7 | Surveyed, appears not NR/SR Eligible | Lack of integrity | BING-33 | | | |
| 78 | | 120 | Jennings St | Village of Endicott | 157.09-2-1 | Surveyed, appears not NR/SR Eligible | Altered; modern materials | END-9 | | | |
| 79 | | 14 | Kot Rd | Town of Union | 127.02-1-22 | Surveyed, appears not NR/SR Eligible | No industrial building/structure visible on site; difficult to access | UNION-9 | | | |
| 80 | | 18 | Kot Rd | Town of Union | 127.02-1-34 | Surveyed, appears not NR/SR Eligible | Significantly altered; lack of integrity | UNION-10 | | | |
| 81 | | 47 | Kot Rd | Town of Union | 110.04-1-5 | Surveyed, appears not NR/SR Eligible | Lack of integrity | UNION-11 | | | |
| 82 | Bates-Troy Laundry Co. | 151 | Laurel Ave | City of Binghamton | 160.29-3-2 | Surveyed, appears NR/SR Eligible | | BING-34 | 5-9 | 1 | Y |
| 83 | | 49 | Leon Ave | Town of Dickinson | 145.09-1-1 | Surveyed, appears not NR/SR Eligible | No industrial building/structure visible on site | DCKSN-2 | | | |
| 84 | | 59 | Leon Ave | Town of Dickinson | 145.05-1-23 | Surveyed, appears not NR/SR Eligible | Lack of integrity; difficult to view from public access | DCKSN-3 | | | |
| 85 | Endicott-Johnson Victory | 59 | Lester Ave | Village of Johnson City | 143.58-1-19 | NR/SR Listed | Johnson City Historic District | JC-15 | 5-20 | 139 | Y |
| 86 | | 31 | Lewis St | City of Binghamton | 160.25-2-26 | NR/SR Listed | Railroad Terminal Historic District | BING-35 | 5-9 | 12 | Y |
| 87 | | 2313 | Lewis St | Town of Union | 157.07-2-19 | Surveyed, appears not NR/SR Eligible | Unremarkable building; modern materials | UNION-12 | | | |
| 88 | | 2320 | Lewis St | Town of Union | 157.07-2-37 | Surveyed, appears not NR/SR Eligible | Significantly altered; lack of integrity | UNION-13 | | | |
| 89 | | 5 | Liberty Ave N | Village of Endicott | 157.09-2-15 | Surveyed, appears not NR/SR Eligible | Altered | END-10 | | | |
| 90 | | 42 | Loughlin Rd | Town of Kirkwood | 146.17-2-3 | Surveyed, appears not NR/SR Eligible | Unremarkable building; altered | KIRK-6 | | | |
| 91 | | 229 | Lower Stella Ireland | Town of Dickinson | 127.83-1-27 | Surveyed, appears not NR/SR Eligible | Does not appear to meet NR criteria; altered | DCKSN-4 | | | |
| 92 | | 289 | Main St | Town of Kirkwood | 211.05-1-5 | Surveyed, appears NR/SR Eligible | Does not appear to meet NR criteria | KIRK-7 | | | |
| 93 | BAE System Controls Inc. | 600 | Main St | Town of Union | 143.62-1-1 | Surveyed, appears not NR/SR Eligible | 7 USNs for building, No Determination | UNION-1 | 5-24 | 130 | N |
| 94 | | 117 | Main St E | Village of Endicott | 157.13-1-28 | Surveyed, appears not NR/SR Eligible | Altered; modern materials | END-11 | | | |
| 95 | | 2009 | Main St E | Town of Union | 157.07-1-13 | Surveyed, appears not NR/SR Eligible | Altered | UNION-14 | | | |
| 96 | | 2011 | Main St E | Town of Union | 157.07-1-12 | Surveyed, appears not NR/SR Eligible | Altered | UNION-15 | | | |
| 97 | | 3120 | Main St E | Town of Union | 157.08-3-6 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | UNION-16 | | | |
| 98 | | 9-11 | Market St | City of Binghamton | 143.59-1-2 | Surveyed, appears not NR/SR Eligible | Unremarkable building; altered | BING-36 | | | |
| 99 | | 35-37 | Milford St | City of Binghamton | 145.79-2-7 | Surveyed, appears not NR/SR Eligible | Did not appear to be historically an industrial building | BING-37 | | | |
| 100 | | 3 | Moeller St | City of Binghamton | 161.21-2-25 | Surveyed, appears not NR/SR Eligible | Does not appear to meet NR criteria | BING-38 | | | |
| 101 | | 182 | Moeller St | City of Binghamton | 145.45-1-25 | Surveyed, appears not NR/SR Eligible | Significantly altered | BING-39 | | | |
| 102 | | 50 | Montgomery St | City of Binghamton | 144.76-1-28 | Surveyed, appears not NR/SR Eligible | Altered; lack of integrity | BING-40 | | | |
| 103 | Montgomery Street Table & | 111-115 | Montgomery St | City of Binghamton | 144.68-1-2 | Surveyed, appears NR/SR Eligible | | BING-41 | 5-10 | 4 | Y |
| 104 | | 88 | N Moeller St | Town of Dickinson | 129.13-1-15 | Surveyed, appears not NR/SR Eligible | No industrial building/structure visible on site; difficult to access | DCKSN-5 | | | |
| 105 | | 403-405 | Nanticoke Ave N | Village of Endicott | 157.05-7-15 | NR/SR Eligible (per NYSHPO) | Does not appear to meet NR criterion for significance | END-12 | | | |
| 106 | | 19 | Nebraska Ave | Town of Union | 157.08-1-34 | Surveyed, appears not NR/SR Eligible | Altered; modern materials | UNION-17 | | | |

| No. | Property Name | Street No. | Street Name | Municipality | Tax ID No. | Significance | Comments | Map Reference | Annotated List Page | Census Tract | Tax Credit Eligibility |
|-----|---------------------------------|------------|----------------|-------------------------|---------------|--------------------------------------|--|---------------|---------------------|--------------|------------------------|
| 107 | | 1 | North Depot St | City of Binghamton | 160.25-2-20 | NR/SR Listed | Railroad Terminal Historic District | BING-42 | 5-10 | 5 | Y |
| 108 | Reynolds, Rogers & Co. (former) | 21 | North Depot St | City of Binghamton | 160.25-2-16 | NR/SR Listed | Railroad Terminal Historic District | BING-43 | 5-10 | 5 | Y |
| 109 | | 1103 | North St | Village of Endicott | 157.06-1-42.1 | Surveyed, appears not NR/SR Eligible | Modern construction | END-13 | | | |
| 110 | IBM Factory Building | 1803 | North St | Village of Endicott | 157.07-1-2 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-14 | 5-17 | 135 | Y |
| 111 | IBM Factory Building #14 | 1701 | North St (A) | Village of Endicott | 157.06-1-43 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-15 | 5-16 | 135 | Y |
| 112 | IBM Factory Building #18 | 1701 | North St (B) | Village of Endicott | 157.06-1-43 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-16 | 5-16 | 135 | Y |
| 113 | IBM Factory Building #41 | 1701 | North St (C) | Village of Endicott | 157.06-1-43 | Surveyed, appears NR/SR Eligible | Contributes to potential IBM Plant No. 1 Historic District | END-17 | 5-16 | 135 | Y |
| 114 | | 4 | Nowlan Rd | Town of Fenton | 129.05-4-2 | Surveyed, appears not NR/SR Eligible | Altered; lack of integrity | FENT-3 | | | |
| 115 | Link Aviation Company | 36 | Nowlan Rd | Town of Fenton | 129.05-4-4 | Surveyed, appears NR/SR Eligible | | FENT-4 | 5-23 | 122.02 | Y |
| 116 | | 131 | Nowlan Rd | Town of Fenton | 129.06-1-40 | Surveyed, appears not NR/SR Eligible | Unremarkable building; modern materials | FENT-5 | | | |
| 117 | | 8308 | NYS Rte 79 | Town of Triangle | 035.07-1-1.11 | Surveyed, appears not NR/SR Eligible | Unremarkable building; modern materials | TRI-1 | | | |
| 118 | | 148 | Oak St | City of Binghamton | 160.32-1-24 | Surveyed, appears not NR/SR Eligible | Does not appear to meet NR criteria; altered | BING-44 | | | |
| 119 | | 66-70 | Olive St | Village of Johnson City | 143.56-1-3 | Surveyed, appears not NR/SR Eligible | Lack of integrity | JC-16 | | | |
| 120 | Endicott-Johnson Company Fair | 1 | Page Ave N | Town of Union | 156.51-1-36 | Surveyed, appears NR/SR Eligible | | UNION-18 | 5-24 | 133.01 | Y |
| 121 | | 2 | Page Ave S | Village of Endicott | 156.12-4-63 | Surveyed, appears not NR/SR Eligible | Significantly altered; lack of integrity | END-18 | | | |
| 122 | Rossville Silk Mills | 122 | Park Ave | City of Binghamton | 176.32-3-21 | Surveyed, appears NR/SR Eligible | | BING-45 | 5-11 | 17 | Y |
| 123 | Gotham Shoe Mnfg. Co. (former) | 129 | Park Ave | City of Binghamton | 176.32-3-24 | Surveyed, appears NR/SR Eligible | | BING-46 | 5-11 | 17 | Y |
| 124 | | 8 | Park St | Village of Windsor | 182.07-2-7 | NR/SR Listed | Significantly altered; modern materials | WIND-1 | | | |
| 125 | Ozalid/Anso Camera Company | 18 | Park St | Village of Johnson City | 143.66-2-47.2 | Surveyed, appears not NR/SR Eligible | Johnson City Historic District | JC-17 | 5-21 | 139 | Y |
| 126 | | 3117 | Pearl St | Town of Union | 141.20-6-7 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | UNION-19 | | | |
| 127 | | 3125 | Pearl St | Town of Union | 141.20-6-8.1 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | UNION-20 | | | |
| 128 | | 1041 | Powers Rd | Town of Conklin | 178.04-1-3 | Surveyed, appears not NR/SR Eligible | Unremarkable building; modern alterations | CONK-2 | | | |
| 129 | | 1743 | Rte 11 | Town of Kirkwood | 211.01-1-1 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | KIRK-8 | | | |
| 130 | | 1755 | Rte 11 | Town of Kirkwood | 211.01-1-3 | Surveyed, appears not NR/SR Eligible | Unremarkable building; significantly altered | KIRK-9 | | | |
| 131 | | 1813 | Rte 11 | Town of Kirkwood | 211.01-1-5 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | KIRK-10 | | | |
| 132 | | 314 | Scarborough Dr | Town of Union | 157.08-7-13 | Surveyed, appears not NR/SR Eligible | Altered | UNION-21 | | | |
| 133 | | 209 | Stage Rd | Town of Vestal | 157.18-1-12 | Surveyed, appears not NR/SR Eligible | Unremarkable building; lack of integrity | VEST-1 | | | |
| 134 | | 142 | State St | City of Binghamton | 160.41-1-6 | Surveyed, appears not NR/SR Eligible | Unremarkable parking garage | BING-47 | | | |
| 135 | | 165 | Susquehanna St | City of Binghamton | 160.50-1-58 | Surveyed, appears not NR/SR Eligible | Altered | BING-48 | | | |
| 136 | | 2 | Titchener Pl | City of Binghamton | 160.23-2-25 | Surveyed, appears not NR/SR Eligible | Partially demolished; lack of integrity | BING-49 | | | |
| 137 | | 72 | Travis Ave | City of Binghamton | 144.36-2-32 | Surveyed, appears not NR/SR Eligible | Significantly altered | BING-50 | | | |
| 138 | | 1-11 | Travis Ave | City of Binghamton | 144.52-1-15 | Surveyed, appears not NR/SR Eligible | Significantly altered | BING-51 | | | |
| 139 | | 4089 | US Rte 11 | Town of Lisle | 006.13-1-5 | Surveyed, appears not NR/SR Eligible | Unremarkable building; modern materials | LISLE-1 | | | |
| 140 | | 10 | Valley St | Town of Union | 142.17-3-61 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | UNION-22 | | | |
| 141 | | 20 | Valley St | Town of Union | 142.17-3-62 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | UNION-23 | | | |
| 142 | | 37 | Valley St | Town of Union | 142.17-3-26 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | UNION-24 | | | |
| 143 | | 341 | Vestal Pkwy E | Town of Vestal | 157.19-1-3 | Surveyed, appears not NR/SR Eligible | Unremarkable building; does not appear to meet NR criteria | VEST-2 | | | |
| 144 | | 3129 | Vestal Rd | Town of Vestal | 158.07-1-4 | Surveyed, appears not NR/SR Eligible | Unremarkable building; significantly altered | VEST-3 | | | |
| 145 | | 3221 | Vestal Rd | Town of Vestal | 158.07-2-13 | Surveyed, appears not NR/SR Eligible | Lack of integrity; does not appear to meet NR criteria | VEST-4 | | | |
| 146 | | 3421 | Vestal Rd | Town of Vestal | 158.07-2-15 | Surveyed, appears not NR/SR Eligible | Modern materials; does not appear to meet NR criteria | VEST-5 | | | |
| 147 | Clark-Cleveland Co. (former) | 20 | Wall St | City of Binghamton | 160.40-2-2 | Surveyed, appears NR/SR Eligible | | BING-52 | 5-11 | 12 | Y |
| 148 | | 183 | Water St | City of Binghamton | 160.40-2-3 | Surveyed, appears not NR/SR Eligible | Unremarkable parking garage | BING-53 | | | |
| 149 | Hull, Grummond & Co. Cigar | 218 | Water St | City of Binghamton | 160.32-2-3 | NR/SR Listed | State Street-Henry Street Historic District | BING-54 | 5-12 | 2 | Y |
| 150 | | 301 | Water St | City of Binghamton | 160.24-4-1 | Surveyed, appears not NR/SR Eligible | Demolished due to fire; USN, no Determination | BING-55 | | | |
| 151 | National Cigar Box Company | 320 | Water St | City of Binghamton | 160.25-1-10 | Surveyed, appears NR/SR Eligible | Appears to contribute to potential expanded downtown HD | BING-56 | 5-12 | 5 | |
| 152 | | 321 | Water St | City of Binghamton | 160.25-1-2 | Surveyed, appears not NR/SR Eligible | Previously determined by SHPO as not NRE | BING-57 | | | |
| 153 | | 326 | Water St | City of Binghamton | 160.25-1-8 | Surveyed, appears not NR/SR Eligible | Altered; lack of integrity | BING-58 | | | |
| 154 | Schuler Hass Electric Corp. | 330 | Water St | City of Binghamton | 160.25-1-7 | Surveyed, appears NR/SR Eligible | Appears to contribute to potential expanded downtown HD | BING-59 | 5-12 | 5 | Y |
| 155 | NY State Electric & Gas Co. | 366 | Water St (A) | City of Binghamton | 144.81-2-12 | Surveyed, appears NR/SR Eligible | Appears to contribute to potential expanded downtown HD | BING-60 | 5-13 | 5 | Y |
| 156 | NY State Electric & Gas Co. | 366 | Water St (B) | City of Binghamton | 144.81-2-12 | Surveyed, appears NR/SR Eligible | Appears to contribute to potential expanded downtown HD | BING-60 | 5-13 | 5 | Y |
| 157 | | 2507 | Wayne St | Town of Union | 141.82-1-14 | Surveyed, appears not NR/SR Eligible | Altered; lack of integrity | UNION-25 | | | |
| 158 | | 26 | Webster St | City of Binghamton | 160.44-4-1 | Surveyed, appears not NR/SR Eligible | Lack of integrity | BING-62 | | | |
| 159 | | 60 | Whitney Ave | City of Binghamton | 144.76-1-22 | Surveyed, appears not NR/SR Eligible | Does not appear to meet NR criteria | BING-63 | | | |